Pictures of Damage

Since Mid October

No Crack in Wall





18 days Later

Water coming out of middle of Road on a Clear day

Morning



Afternoon





No problem with New front Window 3A until Mid-October 2010

Window damaged from Move-Ment



43

Next door has issues





Water Coming up from Street on a Clear day



Looking for cause of issues next door




3A Water Heater Closet



3A bathroom Ceiling



UA Shower grouted & caulked for 3rd time





Floor Moved up — then down

Bedroom Ceiling 01






Hallway New Window 2nd floor damaged (bent) this Molding was New in July or August & was not Spread apart as it is now.




Cracks in New Sheet Rock Below dining AREA Window


3A



3A Cracks under Wall paper on Wall next to Hall Closet


3A pantry Cupboard No longer touches Ceiling







3A Crack in Wall/Ceiling Next to pantry cupboard

3A Crack in Wall in Kitchen







3A door 1 1/8" difference from left side & right side


3A

THIS WE ACTUALLY HEARD CRACK at 3AM. Closet side of Master bedroom


Note: Space in molding



this is the Bedroom side of the 3AM Crack



3A When Wayne's Engineer came in October this Crack was Just A small line in the Right Corner by Ceiling. Now it Moved up & over





3A

This is Kitchen 3A Happened between Christmas and Jan 1

Hallway over 3A Entry






Crack 3B doorway

This is the kind of Cracking We Were told to look for in Movement

Cellar Cracks Much Larger Since October






01/18/2011


01/18/2011

The line is where the floor used to be




This was not like this until sometime in October 2010





3A

This is the same Corner of 3A front Window




Notice Middle Bubble




02/11/2011


02/21/2011

31 Bathroom Ceiling busted up – then down








AGAIN !




34 Master Closet

We heard this one Crack too




3A Hall Way Closet - We heard this one Crack





2B Door

3A Front Wall has moved so far out — the baseboard is no longer covering the edges of Hardwood floor







3A the front wall moved outward - see paint line from when baseboard was painted

C3A the only place the fireplace touches the floor is in the middle





31







When these windows were installed in spring of 2010, the gap between window & trim was not there.




04/05/2011



04/05/2011



good
up
04/05/2011


good
NOT good
I FIX IT
04/05/2011


04/05/2011
Protecto Wrap
1-800-758-9727
www.protectowrap.com
Meets ASTM 2112


04/05/2011
Protecto Wrap
1-800-758-9727
www.protectowrap.com
Meets ASTM 2112


window HAS moved
04/05/2011


window HAD moved
04/05/2011